TachoScan Control

List of changes

Version: 5.3.3

TachoScan Control

List of changes

All Rights Reserved

All rights reserved. No parts of this work may be reproduced in any form or by any means - graphic, electronic, or mechanical, including photocopying, recording, taping, or information storage and retrieval systems - without the written permission of the publisher.

Products that are referred to in this document may be either trademarks and/or registered trademarks of the respective owners. The publisher and the author make no claim to these trademarks.

While every precaution has been taken in the preparation of this document, the publisher and the author assume no responsibility for errors or omissions, or for damages resulting from the use of information contained in this document or from the use of programs and source code that may accompany it. In no event shall the publisher and the author be liable for any loss of profit or any other commercial damage caused or alleged to have been caused directly or indirectly by this document.

The program windows (screenshots) shown within this help file can differ in form and contents from the actual program windows. This can be the case especially when the program version differs from the manual version.

Production:

INELO Polska

ul. Karpacka 24/U2b
43-300 Bielsko-Biała
POLAND
www.inelo.pl

Roadside Check Form - Luxembourg (French language version with Luxemboug tariff)

(menu: Reports -> Roadside Check Form - Luxemburg)

- depending on the type of authorities conducting the control, the logo of police or roadside inspection will be displayed on the report

Update of Polish protocols

In connection with the update of Road Transport Act (http://prawo.sejm.gov.pl/isap.nsf/download.xsp/WDU20190002145/O/D20192145.pdf) protocols were adjusted according to the new legal requirements

(menu: Reports -> Roadside Check Form and Control on the premises protocol)

- the protocol was adjusted to the template imposed by lawmaker (according to: http://prawo.sejm.gov.pl/isap.nsf/download.xsp/WDU20190002145/O/D20192145.pdf
- together with the protocol two attachments are generated:
  - with infringements for a contractor
  - with infringements for a management organ

Changes in descriptions of infringements

(menu: Reports -> Infringements and manipulations)

- descriptions of chosen infringements were updated

Information about license number on reports' printouts

(menu: Reports)

- on the reports' printouts information on the license number of the user who generates the report

New option in program settings

(menu: Settings -> Program settings)

- **treat the speed of 255 km/h from digital tachograph as no data** option was added, it is enabled by default for all language versions of the program, except German language

New language version of the program

- Hungarian language version of the program was added

(menu: Settings -> Program settings)

- a possibility of choosing Hungarian language was added (**Select program language**)

INELO Polska
Spółka z ograniczoną odpowiedzialnością

ul. Karpacka 24/U2b,
43-300 Bielsko-Biała

tel. +48 33 496 58 71
biuro@inelo.pl www.inelo.pl